Case No. 2009-00116

#### KENTUCKY PUBLIC SERVICE COMMISSION

RECEIVED

MAR 1 8 2009

PUBLIC SERVICE
COMMISSION

Water Storage Requirement Deviation Request Application

**807 KAR 5:066, Section 4(4)**: Storage. The minimum storage capacity for systems shall be equal to the average daily consumption.

This form is intended to assist water utilities seeking a deviation from the requirements of 807 KAR 5:066, Section 4(4) and for permission to either maintain less water storage capacity than the average daily consumption or to obtain additional time to attain minimum storage capacity equal to the average daily consumption.

To request a deviation from the requirements of 807 KAR 5:066, Section 4(4), please complete the following application in full.

Othity:	Mckinney water	District				
Addre	ss: 2900 Ky Hwy 1	98, PO Box	7			
City:_	McKinney	State:	Ку.	Zip Code: <sup>40448</sup>		
Telep	hone Number: (606) 3	46-2220		Number of Customers: 1875		
County or Counties served: Lincoln		Casey				
***************************************						
Are yo	ou requesting a deviatio	n:				
( <u>X</u> )	_) To maintain less water storage capacity than the average daily consumption?					
()	_) For additional time to attain minimum storage capacity equal to the average daily					
	consumption?					

#### I. Contact Information

Please provide information for the person to whom correspondence or communications concerning this application should be directed:

Name: Bob Maples	Title:	Manager
Address: 75 Neals Creek Ro	oad	
City: Stanford St	ate: Ky•	Zip Code:40484
Telephone Number: (606) 365-78	328 (home)	606-346-2220 (work)

#### II. Filing Requirements

Please submit an original and seven (7) copies of the completed application to:

Kentucky Public Service Commission

**Executive Director's Office** 

211 Sower Boulevard

Frankfort, Kentucky 40602

Telephone: (502) 564-3940

All correspondence and responses to supplemental information requests should be sent to the above address as well.

Copies of this form may be obtained by visiting the Kentucky Public Service Commission website at <a href="http://psc.ky.gov">http://psc.ky.gov</a> and clicking on the Forms bullet in the Quick Reference, or by contacting George Wakim, Branch Manager, Water & Sewer Branch, at (502) 564-3940.

III. Questionnaire:							
Please answer all o	questions completely	, attach add	litional sheets as necessary.				
1. Provide the ave	erage daily water co	nsumption.	This should include all water				
sold, utility wate	sold, utility water usage, and unaccounted-for-water. following information:						
Average Daily (	Average Daily Consumption: 277,470 gallons						
2. Please provide the following information:							
Total number of	Total number of water storage tanks in the system:3						
Type of Storage	<u>Гаnk</u>		<u>Capacity</u>				
Standpipe (McKinney)		100,000					
Standpipe (Boneyv	ille)		100,000				
Elevated (Ottenh	eim)		100,000				
		***************************************					
		•					
		**************************************					
	The second secon						

3. Please provide a list of all large customers purchasing more than five (5) percent of the utility's average daily consumption. Also indicate which, if any, of these customers can sustain an interruption during emergencies.

The five customers listed are dairy or livestock owners. We are not aware of their water supply including ponds, etc.

0	Dallada	04		0	1	
Customer	<u>Daily Usage</u>		Facility ()No	Capacity	Interruption ⟨ <b>X</b> Yes ( ) No	
Freddie Bratcher	32,516	•		100,000		
Anthony Honaker	30,419	,	s ( ) No	200,000	X Yes () No	
George Spoonamo	e 24,161	Yes	; ( ) No	200,000	💢 Yes()No	
Nell Davis	20,452	X Yes	s ( ) No	200,000	💢 Yes () No	
Boyd Coleman	20,419	<b>∭</b> Yes	s ( ) No	200,000	<b>(X)</b> Yes ( ) No	
		()Yes	s ( ) No		( ) Yes ( ) No	
4. Please provi		ritical healt	hcare facilit  Storage ( ) Yes	Facility ( ) No	by the system.  Capacity	
<ol><li>Please provide the following information:</li><li>Does the utility:</li></ol>						
Produce water? ( ) Yes 💢 No Purchase water? 🦹 Yes ( ) No						
If the utility p	ourchases water	r, please p	rovide the f	ollowing info	ormation:	
Supplier			<u>Averag</u>	e Amount F	Purchased	
City of Stanford Waterworks			7,164,33	33 gallon	s per month	
Eubank Water Sys	stem		1,867,70	00 gallon	s per month	

6. If a supplier has storage capacity or reserves storage capacity for the benefit of your utility, please provide the following information:

<u>Supplier</u>	<u>Capacity</u>	Proximity to Master Meter
Eubank Water System	357,000	1 1/2 miles
Eubank Water System	75,000	1 1/2 miles
MANAGEMENT AND		

- 7. Will your supplier issue your utility a letter of this additional storage capacity specifying whether they can sustain any of your system's interruptions to ensure you adequate continuity of service? (XY) Yes () No If yes, provide a copy of the agreement or letter. (attached)
- 8. Please provide a technical summary of operational deficiencies of the system that are known from experience or that are indicated by hydraulic analysis. This should include a list of outages that occurred in past years, their location, the cause and duration of any outages, customer complaints, areas of low pressure, and the availability of standby equipment, repair equipment, and contractors.

Attachments of outages.

Attachments of customer complaints.

Constant low pressure on KY HWY 518 until installation of pump station with two pumps plus two pumps available for back-up and a generator on standby when needed.

The District keeps a supply of pipe, repair clamps and all materials needed to repair leaks.

The District has two men available at all times plus two men on standby to make repairs day or night.

9. Please provide information on the growth potential for the system. This should include the number of new customers added per year and the possibility of extensive development (i.e. new subdivisions, businesses, etc.)

Due to severs Planning and Zoning restrictions plus the McKinney Water District's boundries, we see no possibility of new subdivisions or any extensive growth in our system.

10. Please describe any planning, to date, to bring the system into compliance with Commission regulations. This should include efforts to secure financing for the construction of additional storage facilities, as well as the estimated compliance date. If no planning has taken place, please explain why.

Due to limited funding of our local government and the fact our state funding is stressed and only supporting funding for programs already in existence, the District is unable to construct additional storage facilities at this time. Also, the District is unable to borrow on a project that would not generate any revenue even if the funds were available.

As of this date we are unable to give even an estimated

date of approaching a lender for additional storage.

IV.	<u>Signature:</u>
-----	-------------------

I have read and completed this application, and to the best of my knowledge, a
the information contained herein is true and correct.
Signed: Bob Maples
Title: MANAger
Date: 3-14-09

CITY OF EUBANK

20 Water Way Eubank, Kentucky 42567

PH: (606) 379-2211 FAX: (606) 379-2023 TDD: 1-800-247-2510

Fey Todd Mayor Bobby Daws City Clerk

12/10/08

To Whom It May Concern:

6063792211

The water supplied by the Eubank Water System to Mckinney Water, is supplied by 432,000 gallons of storage.

**Bobby Daws** 

Manager



DATE: 3-7-07
LOCATION OF INTERRUPTION: George Kliott, New Construction
TIME WATER WAS TURNED OFF. 9015 A m
CAUSE OF LINE BREAKAGE: Contractor & trencher for Blect.
SIZE OF LINE: 6" PLASTIC IRON OTHER Franzite
ESTIMATED AMOUNT OF WATER LOSS: 1000
DAMAGE CAUSED BY REPAIR OR INTERRUPTIÓN:
·
TIME SERVICE WAS RESTORED: 11:30 A. V.
MATERIAL USED ON JOB: / 24" X 6" 55 Repair Clamp
PERSONNELL AT JOB SITE: DANNY 30 FFMAN & Crew
· 33. ///
REMARKS: Contractor paid Bill 800+dollArs



DATE: 4-6-07
LOCATION OF INTERRUPTION: Huy. 698 IN Creek TIME WATER WAS TURNED OFF: 9:00 A.M.
TIME WATER WAS TURNED OFF: 9:00 A.M.
CAUSE OF LINE BREAKAGE: 55 LOOSE LOOSE
SIZE OF LINE: 4'' PLASTIC IRON OTHER
ESTIMATED AMOUNT OF WATER LOSS: 10,000
DAMAGE CAUSED BY REPAIR OR INTERRUPTION:
TIME SERVICE WAS RESTORED: 5:30 P. HAd to Anchor
TIME SERVICE WAS RESTORED: 5:30 P. HAD to Anchor L'NR AND WAIT ON CONCrete - 7405.
MATERIAL USED ON JOB: 7 Soucrete Log Chil
•
PERSONNELL AT JOB SITE: Sott CottmAN
DANNY COTEMAN & Crew.
REMARKS:



. 14
DATE: 6-07
LOCATION OF INTERRUPTION: MCKINNEY Grade School
TIME WATER WAS TURNED OFF: 7,33 14, 17x
CAUSE OF LINE BREAKAGE: Directional Boring is out line
SIZE OF LINE: 2'' PLASTIC IRON OTHER
ESTIMATED AMOUNT OF WATER LOSS: 60 800
DAMAGE CAUSED BY REPAIR OR INTERRUPTION:
, .
·
TIME SERVICE WAS RESTORED: 2.00 P. M.
MATERIAL USED ON JOB: 3 X 2'' P.V.C. pipe /X 12.5''  SS Repair (Am
55 Repair Class
PERSONNELL AT JOB SITE: DANNY COFFMAN & Crew
Soft Coteman & Crew.
REMARKS:
REPORTED.



LOCATION OF INTERRUPTION: 4245 - Bethany Berry - Arco Cress properties was turned off; 1:30 P.M.  CAUSE OF LINE BREAKAGE: 3" Service line bent too much At  SIZE OF LINE: 3" PLASTIC IRON OTHER ESTIMATED AMOUNT OF WATER LOSS: 1000  DAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED: 3:15 P. M.  MATERIAL USED ON JOB: 5" X 3" Froise line At corp. Stap  PERSONNELL AT JOB SITE: DANNY CAFTAIN & Crew  TOTAL CREMARKS:  REMARKS:	DATE: 1-7-08
SIZE OF LINE:  SIZE OF LINE:  PLASTIC IRON OTHER  ESTIMATED AMOUNT OF WATER LOSS:  PAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED:  MATERIAL USED ON JOB: 5 X 1/2 Zarvice line At corp. Stap  MATERIAL USED ON JOB SITE:  PERSONNELL AT JOB SITE:  MAN DE GARD & Crew  TO L.	LOCATION OF INTERRUPTION: 4245 - RethANY Berry - Arco Cress DOP
SIZE OF LINE:  SIZE OF LINE:  PLASTIC IRON OTHER  ESTIMATED AMOUNT OF WATER LOSS:  DAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED:  MATERIAL USED ON JOB: 5 X 1/2 Zervice line At corp. Stap  MATERIAL USED ON JOB SITE:  PERSONNELL AT JOB SITE:  MAN NY CATARA + Crew  JOHN NY CATARA + Crew	TIME WATER WAS TURNED OFF: 1:30 P.M.
SIZE OF LINE:  SIZE OF LINE:  PLASTIC IRON OTHER  ESTIMATED AMOUNT OF WATER LOSS:  DAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED:  MATERIAL USED ON JOB: 5 X 1/2 Zervice line At corp. Stap  MATERIAL USED ON JOB SITE:  PERSONNELL AT JOB SITE:  MAN NY CATARA + Crew  JOHN NY CATARA + Crew	CAUSE OF LINE BREAKAGE: 34" Spraige line bent too much At.
DAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED: 3:15 P. M.  MATERIAL USED ON JOB: 5 X 3/1 Zervice line At corp. Stap  PERSONNELL AT JOB SITE: JANNY Coffant + Creu  The service was restored: 3:15 P. M.  PERSONNELL AT JOB SITE: JANNY Coffant + Creu  The service was restored: 3:15 P. M.  The service was restored: 3:1	COLDI TARI
DAMAGE CAUSED BY REPAIR OR INTERRUPTION:  TIME SERVICE WAS RESTORED: 3:15 P. M.  MATERIAL USED ON JOB: 5 X 3/1 Zervice line At corp. Stap  PERSONNELL AT JOB SITE: JANNY Coffant + Creu  The service was restored: 3:15 P. M.  PERSONNELL AT JOB SITE: JANNY Coffant + Creu  The service was restored: 3:15 P. M.  The service was restored: 3:1	SIZE OF LINE: 2/ PLASTIC / IRON OTHER
MATERIAL USED ON JOB: 5'X 30" From Stap  PERSONNELL AT JOB SITE: DANNY Offman + Crew  TO A STANDARD TO THE STA	
MATERIAL USED ON JOB: 5'X 30" From se line At corp. Stap  MATERIAL USED ON JOB: 5'X 30" From se line At corp. Stap  PERSONNELL AT JOB SITE: DANNY COFFRAN + Crew  D. L.	
MATERIAL USED ON JOB: 5'X 3" Ernice line At corp. Stap  MATERIAL USED ON JOB: 5'X 3" E	
MATERIAL USED ON JOB: 5'X 3" Ernice line At corp. Stap  MATERIAL USED ON JOB: 5'X 3" E	21120
PERSONNELL AT JOB SITE: DANNY COFFMAN + Crew	TIME SERVICE WAS RESTORED: 3:15 /. YV 1
PERSONNELL AT JOB SITE: DANNY COFFMAN + Crew	
PERSONNELL AT JOB SITE: DANNY COFFMAN + Crew	
PERSONNELL AT JOB SITE: DANNY COFFMAN + Crew	
PERSONNELL AT JOB SITE: DANNY COFFMAN + Crew	MATERIAL USED ON JOB: 5 X // Eroice live At corp. Stap
	14 brass Couplet
	PERSONNELL AT JOB SITE: PANNY CATDAN + Crew
REMARKS:	
REMARKS:	17.4
REMARKS:	·
	REMARKS
	KEPIKKO .



PATE: 7-13-08	
LOCATION OF INTERRUPTION: PichArd Crawley	
TIME WATER WAS TURNED OFF: 4315 P. Mo	_
CAUSE OF LINE BREAKAGE: P. E. CC. Crew Bored through	
P. pe ( P.V.C.)	
SIZE OF LINE: PLASTIC IRON OTHER	
ESTIMATED ANOUNT OF WATER LOSS: 3 000	
PAMAGE CAUSED BY REFAIR OR INTERRUPTION:	
TIME SERVICE WAS RESTORED. 5: ND P. M.	<b>,</b>
	_
	-
MATERIAL USED ON JOB; 5 X 4" PU.C., 2 X 12-5"	
Full Circle Clamps	
The Chings	
PERSONNELL AT JOB SITE: DANNY CAFFINAN & Crew of 2	
B. Maples	
$\bigcap_{i=1}^{n} A_{i}A_{i}$	
ZI ZY NV	
REMARKS	
NC. IIII	
	-
†	



PATE: 8-16-8
LOCATION OF INTERRUPTION: Huy 698 GR Church
TIME WATER WAS TURNED OFF: W. AIM.
CAUSE OF LINE BREAKAGE: HEAVY POCKS
SIZE OF LINE: 4 PLASTIC IRON OTHER
ESTIMATED ANOUNT OF WATER LOSS: 5000
PANAGE CAUSED BY REPAIR OR INTERRUPTION:
TIME SERVICE WAS RESTORED. 4:00 P. M.
SERVICE WILD RESTORED.
·
MATERIAL USED ON JOB: 60 6" P.V.C. INCRESEMENT
4"PUC, 2X 4" POMAC Complers, 746
Concrete
FERSONNELL AT JOB SITE: DANNING COFFINAN + Grew of 3
B MADLES
REMARKS.



PATE: 2-14-08			,		
LOCATION OF INTERRUPTION:	3435	Kuh	Jun. 193	?	
TIME WATER WAS TURNED OFF	8 00 A	m!	1	`	
CAUSE OF LINE BREAKAGE:	Broadbi	and or	enst, C	Trew	
SIZE OF LINE: 40	PLASTIC_	- <u> </u>	TRON	OTHER	
ESTIMATED AMOUNT OF WATER	LOSS:	0,000			
PAMAGE CAUSED BY REPAIR O		, ,			
TIME SERVICE WAS RESTORED	. 2:00	P.M.			The second secon
MATERIAL USED ON JOB: /	124"	G.11	Circle	PROFIT	Clamo
		,-0011		No.	
	•				
PERSONNELL AT JOB SITE:	DANNIS	Coff	MAN Y	· Crew o	F 3
	Cott	of the	AN + C	Trew of	) ·
	1500				·
REMARKS.					
					entergradus representativos establisticas de participantes establisticas de participantes establisticas de par
			•		



DATE: 1-31-08
LOCATION OF INTERRUPTION: BONEYVILLE School Ro.  TIME WATER WAS TURNED OFF: 1:00 PM.
TIME WATER WAS TURNED OFF:
CAUSE OF LINE BREAKAGE: Rock
SIZE OF LINE: / PLASTIC IRON OTHER
ESTIMATED AMOUNT OF WATER LOSS: 300 gal.
DAMAGE CAUSED BY REPAIR OR INTERRUPTION:
1
·
TIME SERVICE WAS RESTORED: 2:00 PM.
MATERIAL USED ON JOB: two X 1" Brass Couplers - 3'X1"  Service Line
Service Line
,
PERSONNELL AT JOB SITE: DANNY COFFINAN & Crew Baples
REMARKS: only ( ) cuctomer out of water for
1 pr.

Page 1 of 1

### **PSC Consumer Inquiry System**

Complaint:	2009-01280	Entry Date:	2/27/2009	Closed Date:		Contact Type:	Hotline		
Name:	Cornelius, Anthony			Utility:	Utility: McKinney Water Distri				
Address:	1316 Ky Hwy 6			Utility Nbr:	25300	Location:	Residence		
Carmer	Waynesburg, I	\Y 4U489		Utility Type:	Water Districts	3			
County: Lincoln  Home: (606) 669-5147 Work:				Reason:	Service quality/repair ( Service outage/interruption ) (none) ( (none) )				
Fax:	Fax: CBR Nbr:				Complaint referred by:				
Cell:	En	nail:		•	-				
Contacted U	tility? 🔽	Spoke with:	Customer ser	vice					
		Cust Relations	s: Failed To Co	rrect Problem					
Utility Contact				Contact's					
Preliminary De Service outag	e			Other Contact	s:	,			
Processor:	MATT.RHODY		. 🗀	0	. —	0	П		
See File		Case Related		Staff Referra		Confidential	<u></u>		
Info Only	ш	Formal Form	ISLLI	Ref to Util		Customer Satisfied	Yes O No O		
		·							
-		•		Rhady		0	H27/09 Was OUH		
e calle	ad Bol	- lack	& after	Robe a	explaine	ed to	him.		
t Out	suppli	er, Ei	back -	had a s	Deale and	titats.	why t		
				ater Ra					
	RACdy								
him n	r.	)							